

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2024

Submitted Date:

04/29/2024

Document Number:

696306293

FIELD INSPECTION FORM

Loc ID 433216 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433208	WELL	PR	12/31/2013	OW	123-37537	ROHN STATE LD09-67-1HN	PR
433210	WELL	PR	12/29/2013	OW	123-37539	ROHN STATE LD09-66HN	PR
433211	WELL	PR	09/01/2023	OW	123-37540	ROHN STATE LD09-66-1HN	PR
433213	WELL	PR	09/01/2023	OW	123-37542	ROHN STATE LD09-67HN	PR
433408	WELL	PR	01/14/2015	OW	123-37618	ROHN STATE LD10-67HN	PR
433419	WELL	SI	12/01/2022	OW	123-37628	ROHN STATE LD10-66-1HN	SI
433421	WELL	PR	01/15/2015	OW	123-37630	ROHN STATE LD10-67-1HN	PR
433422	WELL	PR	01/15/2015	OW	123-37631	ROHN STATE LD10-66HN	PR

General Comment:

This is a Well PAD Inspection ONLY

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:	Gas Lift Injection Meter House		
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 433208 Type: WELL API Number: 123-37537 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433210 Type: WELL API Number: 123-37539 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433211 Type: WELL API Number: 123-37540 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433213 Type: WELL API Number: 123-37542 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433408 Type: WELL API Number: 123-37618 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433419 Type: WELL API Number: 123-37628 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: SI
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433421 Type: WELL API Number: 123-37630 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 433422	Type: WELL	API Number: 123-37631	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR	
Corrective Action:	Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine Field Inspection	petrie	04/29/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306294	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528657