

Inspection Photos
Location Name: Godsey 43-20
API Number: 125-08461



1. Lease sign at well location.



2. View of wellhead with straw bales visible at fencing.

Inspection Photos
Location Name: Godsey 43-20
API Number: 125-08461



3. View looking down grade at repaired erosion channeling.




4. View of straw bales and mulch outside fencing.

Inspection Photos
Location Name: Godsey 43-20
API Number: 125-08461



5. View of repaired erosion looking down slope from well.



6. View of repaired erosion looking up slope towards well.