

Inspection Photos

04/29/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334899

Inspection Doc: 696205774

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334899



Photo 1: Photo taken from the east end of the Location, facing southwest and west. Photo provides an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334899



Photo 2: Photo taken from the separator equipment on the southwest end of the Location. Photo shows unmarked anchor on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334899



Photo 3: Photos taken from the southern interim areas of the Location. Photos shows interim areas that are bare and unvegetated. Additional reclamation required within these areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334899



Photo 4: Photo example showing interim areas. Interim areas on the west, north and east end of the Location have met 1003.e revegetation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334899



Photo 5: Photo taken from the Location entrance, facing south. Operator has placed a thick layer of gravel has been placed at the Location entrance as a "VTC"; aggregate appears to be single sized material- BMP has not been constructed with course multiangular rock of appropriate size; BMP does not appear to be per good engineering practices and is unlikely to be effective during wet or muddy conditions; sediment tracking/transport evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources