

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

04/04/2024

Document Number:

403499251

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10575 Contact Person: James Miller  
Company Name: 8 NORTH LLC Phone: (720) 984-7460  
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com  
City: DENVER State: CO Zip: 80202  
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes  No

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 421212 Location Type: Production Facilities  
Name: Fabrizio PC Number: GK33-99HZ Tank  
County: WELD  
Qtr Qtr: NWSW Section: 33 Township: 11N Range: 61W Meridian: 6  
Latitude: 40.878330 Longitude: -104.219200

Description of Corrosion Protection

8 North's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, 8N will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. 8N retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

8 North's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, 8N ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 462574 Flowline Type: Wellhead Line Action Type: Out of Service

**OFF LOCATION FLOWLINE REGISTRATION**Equipment at End Point Riser: Separator**Flowline Start Point Location Identification**Location ID: 310705 Location Type: Well Site Name: LARI-611N61W Number: 33NWSWCounty: WELD No Location IDQtr Qtr: NWSW Section: 33 Township: 11N Range: 61W Meridian: 6Latitude: 40.876670 Longitude: -104.217720Equipment at Start Point Riser: Well**Flowline Description and Testing**Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000Bedding Material: Native Materials Date Construction Completed: 01/02/2009Maximum Anticipated Operating Pressure (PSI): 180 Testing PSI: 180Test Date: 09/25/2018**OFF LOCATION FLOWLINE Out of Service**Date: 05/17/2023 Entire Line Removal Partial Line Removal**Description of Out of Service:**

The flowline servicing the Lari 12-33 (05-123-26841) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 7/20/2022.

**FLOWLINE FACILITY INFORMATION**Flowline Facility ID: 462575 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_**OFF LOCATION FLOWLINE REGISTRATION**Equipment at End Point Riser: Separator**Flowline Start Point Location Identification**Location ID: 310705 Location Type: Well Site Name: LARI-611N61W Number: 33NWSWCounty: WELD No Location IDQtr Qtr: NWSW Section: 33 Township: 11N Range: 61W Meridian: 6Latitude: 40.876670 Longitude: -104.217720Equipment at Start Point Riser: Well**Flowline Description and Testing**Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000Bedding Material: Native Materials Date Construction Completed: 11/11/2007Maximum Anticipated Operating Pressure (PSI): 350 Testing PSI: 350Test Date: 09/25/2018

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: \_\_\_\_\_

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

\_\_\_\_\_

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 462576 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 410057 Location Type: Well Site

Name: FABRIZIUS-611N61W Number: 33SENW

County: WELD No Location ID

Qtr Qtr: SENW Section: 33 Township: 11N Range: 61W Meridian: 6

Latitude: 40.880050 Longitude: -104.212890

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: Native Materials Date Construction Completed: 07/07/2009

Maximum Anticipated Operating Pressure (PSI): 220 Testing PSI: 220

Test Date: 09/25/2018

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: \_\_\_\_\_

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

\_\_\_\_\_

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 462573 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 302848 Location Type: Well Site

Name: FABRIZIUS-611N61W Number: 33SESW

County: WELD No Location ID

Qtr Qtr: SESW Section: 33 Township: 11N Range: 61W Meridian: 6

Latitude: 40.873000 Longitude: -104.212990

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 03/24/2009  
Maximum Anticipated Operating Pressure (PSI): 190 Testing PSI: 190  
Test Date: 09/25/2018

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: \_\_\_\_\_

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

\_\_\_\_\_

**OPERATOR COMMENTS AND SUBMITTAL**

Comments Form 44 filed to report STATUS CHANGE notification. The following flowline(s) are now out of service:  
12326841FL: services the Lari 12-33 (05-123-26841)  
Pressure test(s) attached.  
All other flowlines will remain as previously reported.  
Updated GIS data attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 04/04/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved:  **Director of ECMC** Date: 5/1/2024

**CONDITIONS OF APPROVAL, IF ANY LIST**

**COA Type**

**Description**

--	--

**ATTACHMENT LIST**

**Att Doc Num**

**Name**

403499251	Form44 Submitted
403650696	OFF-LOCATION FLOWLINE GIS SHP
403742809	PRESSURE TEST

Total Attach: 3 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)