

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Mesa/C23-697

Location ID: 335512

Date: 4/25/2024



Location Entrance – Photo #00872



Wellheads – Photo #00880

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Mesa/C23-697

Location ID: 335512

Date: 4/25/2024



Separators – Photo #00874



Tank Battery – Photo #00873

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Mesa/C23-697

Location ID: 335512

Date: 4/25/2024



ECD – Photo #00875



Meter House – Photo #00885

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Mesa/C23-697

Location ID: 335512

Date: 4/25/2024



Trash/Debris – Photo #00877



Trash/Debris – Photo #00878

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Mesa/C23-697

Location ID: 335512

Date: 4/25/2024



Trash/Debris – Photo #00879



Debris – Photo #00887

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Mesa/C23-697

Location ID: 335512

Date: 4/25/2024



Stored Equipment/Debris – Photo #00882



Stored Supplies/Equipment – Photo #00890

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Mesa/C23-697

Location ID: 335512

Date: 4/25/2024



Open-Ended Line/Stored Equipment/Trash – Photo #00883



Open-Ended Line – Photo #00884

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Mesa/C23-697

Location ID: 335512

Date: 4/25/2024



Open-Ended Load Line/Stored Equipment – Photo #00889



Lack of Stabilization – Photo #00891

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Mesa/C23-697

Location ID: 335512

Date: 4/25/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00892**



Unsecured Separator – Photo #00876

