

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2024

Submitted Date:

05/01/2024

Document Number:

707602636**FIELD INSPECTION FORM**Loc ID 310485 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email   | Comment                         |
|--------------|-------|---|---------------------------------|
| ,            |       | rbucogccinspectionreports@c<br>hevron.onmicrosoft.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 293116      | WELL | TA     | 01/13/2022  | OW         | 123-26466 | TREBOR B 12-19 | PA          |

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
 Well(s): 1: Plugged & Abandoned | PA.  
 Battery: Abandoned. ALL equipment has been removed.  
 Abandoned Battery SE corner GPS coordinates: 40.416740 / -104.505896

Abandoned Centralized Battery formerly served 2 Location IDs  
 (326857, 310485).  
 (Well(s): 1: Temporarily Abandoned | TA ; 1: Plugged & Abandoned | PA).

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

| Type   | Area | Volume |  |  |
|--|------|--------|--|--|
| In Containment: No                                     |      |        |  |  |
| Comment:   |      |        |  |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |  |

Equipment:

|                    |     |  |                 |
|--------------------|-----|--|-----------------|
| Type: Plunger Lift | # 0 |  | corrective date |
| Comment:           |     | Plugged & Abandoned   PA. Equipment removed. |                 |
| Corrective Action: |     | Date:  |                 |

Venting:

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Flaring:

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 293116 Type: WELL API Number: 123-26466 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p><b>CECMC Inspection Report Synopsis:</b></p> <p>On TUE 04/30/2024 at approximately 10:23 hrs. I, Bret Evins, conducted an onsite inspection at:<br/>Operator Name: NOBLE ENERGY INC<br/>Location Name: TREBOR B-65N64W/12SEW<br/>Location ID: 310485<br/>Well Name(s) &amp; API:<br/>Reference:<br/>See "Inspected Facilities" section on page 1 of this Field Inspection Report.<br/>Location County: Weld County, Colorado<br/>Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed:<br/>Well(s): 1: Plugged &amp; Abandoned   PA.<br/>Battery: Abandoned. ALL equipment has been removed.<br/>Abandoned Battery SE corner GPS coordinates: 40.416740 / -104.505896</p> <p><b>WELL STATUS COMMENT:</b><br/>Plugged &amp; Abandoned   PA.<br/>Form 6-SRA on file. Plugging, cut/cap date: 01/29/2024. Approved.<br/>Plugged &amp; Abandoned   PA well GPS coordinates: 40.417253 / -104.503073</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p> | evinsb | 05/01/2024 |

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 707602637    | Site photo(s) | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6532308">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6532308</a> |