

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2024

Submitted Date:

05/01/2024

Document Number:

702403403

FIELD INSPECTION FORMLoc ID 419768 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

22 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298987	WELL	SI	06/01/2022	OW	123-29219	BADDING 40-26	SI
298988	WELL	SI	06/01/2022	OW	123-29220	BADDING 9-26	SI
298991	WELL	SI	06/01/2022	OW	123-29223	BADDING 20-26	SI
299175	WELL	SI	06/01/2022	OW	123-29281	BADDING 16-26	SI
419778	WELL	SI	06/01/2022	GW	123-32344	BADDING 15-26SX	SI
419782	WELL	SI	06/01/2022	GW	123-32347	BADDING 38-26	SI
419784	WELL	SI	06/01/2022	GW	123-32349	BADDING 10-26SX	SI

General Comment:[This is a Multi-well pad inspection.](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate x 7		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	adequate x 7	Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Ag panel		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 7		corrective date
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	electric motors		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	electric panels, meter box and transformers		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 298987 Type: WELL API Number: 123-29219 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI & on the inactive well list, Form 06A Doc # 403108165.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/06/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: Submit test results to the ECMC, exposed at surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 298988 Type: WELL API Number: 123-29220 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI & on the inactive well list, Form 06A Doc # 403108165.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/06/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment: Submit test results to the ECMC.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 298991 Type: WELL API Number: 123-29223 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI & on the inactive well list, Form 06A Doc # 403108165.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/06/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment: Submit test results to the ECMC, exposed at surface.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299175 Type: WELL API Number: 123-29281 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: [SI & on the inactive well list, Form 06A Doc # 403108165.](#)

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/06/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: [Submit test results to the ECMC, exposed at surface](#)

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419778 Type: WELL API Number: 123-32344 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: [SI & on the inactive well list, Form 06A Doc # 403108165.](#)

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/06/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment: [Submit test results to the ECMC, exposed at surface](#)

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419782 Type: WELL API Number: 123-32347 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: [SI & on the inactive well list, Form 06A Doc # 403206945.](#)

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/06/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: [Submit test results to the ECMC, exposed at surface](#)

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419784 Type: WELL API Number: 123-32349 Status: SI Insp. Status: SI

Idle Well			
Purpose: <input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment: <input type="text" value="SI & on the inactive well list, Form 06A Doc # 403108165."/>			
Corrective Action: <input type="text"/>		Date: _____	

BradenHead			
Date of Last Brhd Test: <input type="text" value="12/21/2023"/>		Annual Brhd Completed? <input type="text" value="No"/>	
Last Brhd Test Results		Initial Surf Csg Pressure: <input type="text" value="1"/>	Fluid Type: <input type="text" value="NONE"/>
		End Surf Csg Pressure: <input type="text" value="0"/>	
Comment: <input type="text" value="Submit test results to the ECMC, exposed at surface"/>			
Corrective Action: <input type="text"/>		Date: _____	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>This is a Routine Field Inspection. Any Corrective Actions from previous inspections not addressed are still applicable.</p> <p>Weather:Sunny & clear</p> <p>Location: mostly dry with some mud</p>	revasr	05/01/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702403406	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6532517