

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No
 Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type:	Other	#		corrective date
Comment:	Rig, pump, work tanks and support equipment are grounded.			
Corrective Action:			Date:	
Type:	Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.			
Corrective Action:			Date:	
Type:	Flow Line	# 1		
Comment:	OOSLAT			
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:

Date:

Inspected Facilities

Facility ID: 251623 Type: WELL API Number: 123-19426 Status: TA Insp. Status: WK

Cement

Cement Contractor

Contractor Name: Ranger Energy

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): 115 sxs

Good Return During Job: YES

Cement Type: Class G Neat 15.8#

Comment: EOT @ 2236' KB, MIRU Ranger Energy cementers, mix and pump 115 sxs Class G Neat 15.8 ppg cement slurry (23.5 bbls total), displace tbq with 18 bbls of fresh water, RD cementers, lay down tbq to 1700' KB and reverse clean, POOH with remaining tbq.

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697009445	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6532503