

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2024

Submitted Date:

05/01/2024

Document Number:

707602644

FIELD INSPECTION FORMLoc ID 323771 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323771	LOCATION	AC			-	TREBOR-65N64W 12NWNW	IO

General Comment:

This is a BATTERY inspection.
Well(s): 2: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs
(323771, 326856).
(Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery serves 1 Tank Battery Facility ID
(Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707602640 and/or Location ID #323771
for TA Well(s) info.
B.) Field Inspection Report doc. #707602642 and/or Location ID #326856
for TA Well(s) info.
C.) Field Inspection Report doc. #707602644 and/or Location ID #323771
for Battery / Facility, Equipment info.

Location				
<u>Lease Road:</u>				
Type	Access			
comment:	Adequate			
Corrective Action				Date:
Overall Good: <input type="checkbox"/>				
<u>Signs/Marker:</u>				
Type	BATTERY			
Comment:	OOSLAT applied at Battery equipment.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: _____
Overall Good: <input type="checkbox"/>				
<u>Spills:</u>				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
<u>Fencing/:</u>				
Type	IGNITOR/COMBUSTOR			
Comment:	Barbed wire.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Barbed wire. Surrounded by earth berms.			
Corrective Action:				Date:
Type	TANK BATTERY			
Comment:	Braided wire.			
Corrective Action:				Date:
<u>Equipment:</u>				
Type: Bird Protectors		# 3		corrective date
Comment:				
Corrective Action:				Date:
Type: Emission Control Device		# 2		
Comment:	1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF Shut-down. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: OFF Shut-down.			

Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Battery site: 2: ECD scrubber(s).		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Sales: Calibration card(s) indicates calibration <= 1 year. (DCP). Last calibration: 03/22/2024. Inactive, NO production.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 2 Location IDs (323771, 326856). (Well(s): 2: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	53 Bbls.

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.419731,-104.503361	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).						
Corrective Action:					Date:	
<u>Wells Served By Facilities Above</u>						
API Number		AirsID				
123-13500		API Number				
123-13775		AirsID				
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	323771	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	IO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On TUE 04/30/2024 at approximately 11:02 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: TREBOR-65N64W/12NWNW Location ID: 323771 Well Name(s): See photo(s) #6 attached to this report. API: *See "Wells Served By Facilities Above" sec on pg. 4, and/or photo(s) #6 attached to this report. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 2: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/01/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602645	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6532577