

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 9-30 Pad

Location # 324012



Apr 25, 2024 at 12:54:35 PM
CO

Photo # 5083 From entrance to location



Apr 25, 2024 at 12:57:47 PM
CO

Photo # 5084 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 9-30 Pad

Location # 324012



Photo # 5085 Location



Photo # 5086 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 9-30 Pad

Location # 324012



Photo # 5087 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 5088 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules