

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



Photo # 5368 From entrance to location



Photo # 5369 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



Photo # 5370 Location

Photo # 5371 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



Photo # 5372 Location



Photo # 5373 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



Photo # 5374 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 5375 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B Pad

Location # 311685



**Photo # 5376 PRV vent line does not comply with CECMC
pressure safety device rules**