

# Inspection Photos

Loc: 380504

Operator: CHACO ENERGY COMPANY

Inspection Date: 5/1/2024

County: CHEYENNE




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east along the access road. Topsoil was not adequately salvaged and soils are heavily compacted along the road.



Inspection Photos



Photo 2. Facing east toward the location. .



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:380504 | Date: 5/1/2024

## Inspection Photos



**Photo 3.** The soils are heavily compacted and were not protected.



## Inspection Photos



**Photo 3.** Facing north at the west side of the location. There is a small ~2ft. tall topsoil pile which is insufficient and not stabilized.



## Inspection Photos



**Photo 4.** The backhoe onsite is leaking oil which needs to be cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:380504 | Date: 5/1/2024

Inspection Photos



**Photo 6.** Northwest corner facing southwest.



## Inspection Photos



**Photo 7.** Northeast corner facing south. There are no stormwater controls around the location and soil pile is not stabilized.



Inspection Photos



**Photo 8.** Facing southwest toward the wellhead.



## Inspection Photos



**Photo 9.** Facing toward the open top tank. There are stained soils shown in the circled area near the tank..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:380504 | Date: 5/1/2024

Inspection Photos



**Photo 10.** There is no netting on the open top tank for wildlife bird protection.



## Inspection Photos



**Photo 11.** Facing northeast at the location.

