



00204721

WELL SITE INSPECTION FORM

WELL NAME Doll Estate #1 API NUMBER 05 - -
OPERATOR Mark Powell PERMIT NUMBER _____
LOCATION NW SW 14-7N-58W COUNTY Well
FIELD Raymer INSPECTOR SP

AL/PA/DA INSPECTION RESULTS:

PASS(Y) _____ FAIL(N) _____ DATE _____ FN _____ FD _____ WO _____

WELL STATUS:

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____

MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____

BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION 1/20/89

COMMENTS 4 1/2 csg wedged to valve - well under slight vacuum

- appears to have cont. dumped down csg, little cont on outside

of csg., dirt base for old jack needs leveling.

Risers from separator need to be cut off, 1000 gal cont skin

tank, tank site and skim pit (10' x 15') needs leveling.

Pit used as dump site, 1/2 full

✓