

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2024

Submitted Date:

05/02/2024

Document Number:

704900144

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
397405 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: _____ 1 _____
Name of Operator: UNKNOWN _____
Address: XXXXXXXXXXXXXXXXXXXX _____
City: _____ XXXXX _____ State: _____ XX _____ Zip: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 _____ Number of Comments
0 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229543	WELL	TA	01/01/1999	LO	103-07199	SILVER KING-PAN AM-HAYES 5-27 (OWP)	EI

General Comment:

On April 2, 2024 ECMC OWP West EPS Jim Hughes conducted an environmental field inspection of the UNKNOWN – 1 Silver King-Pan Am-Hayes #5-27 (OWP). For the most recent field inspection report of this facility, please refer to document #401500708. Cottonwood Consulting was on location during this inspection. The purpose of this site visit was to document current conditions at this location prior to the ECMC OWP plugging the well.

Inspected Facilities

Facility ID: 229543 Type: WELL API Number: 103-07199 Status: TA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>On April 2, 2024 ECMC OWP West EPS Jim Hughes conducted an environmental field inspection of the UNKNOWN – 1 Silver King-Pan Am-Hayes #5-27 (OWP). For the most recent field inspection report of this facility, please refer to document #401500708. Cottonwood Consulting was on location during this inspection. The purpose of this site visit was to document current conditions at this location prior to the ECMC OWP plugging the well.</p> <p>No methane was detected during the pre-plugging methane assessment.</p>	hughesjo	05/02/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
704900145	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6534002