



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API 057-06598 Rabbit Ears Photo taken on 3/28/24
Photo #1 sign at wellhead. Pumping unit.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API 057-06598 Rabbit Ears Photo taken on 3/28/24
Photo #2 . Pumping unit was SI at the time of inspection.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API 057-06598 Rabbit Ears Photo taken on 3/28/24

Photo #3 Combustors, they did not appear to be fired at the time of inspection.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API 057-06598 Rabbit Ears Photo taken on 3/28/24
Photo #4 Tank battery .



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API 057-06598 Rabbit Ears Photo taken on 3/28/24
Photo #5 Secondary containment .



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API 057-06598 Rabbit Ears Photo taken on 3/28/24
Photo #6 3 AGT's in secondary containment.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API 057-06598 Rabbit Ears Photo taken on 3/28/24
Photo #7 Production equipment in dirt berm .