

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2024

Submitted Date:

05/02/2024

Document Number:

694500645**FIELD INSPECTION FORM**Loc ID 449274 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10805Name of Operator: FULCRUM ENERGY OPERATING LLCAddress: 240 SAINT PAUL STREET SUITE 502City: DENVER State: CO Zip: 80206**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Blohm, Justin	520-820-2380	justin.blohm@fulcrumeo.com	
Penner, Annalee	417-773-2341	annalee.penner@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449275	WELL	PR	10/01/2020	OW	057-06598	REU 0681 1-23H2	EI

General Comment:

On 3/28/2024 ECMC staff, Kris Neidel inspected Rabbit Ears location. The location was mostly covered in snow and puddled water. The well was SI at the time of inspection. It appears that tanks have been removed from inside the engineered secondary containment. ECMC has not received a Remediation workplan for the decommissioning of this facility. Corrective Action: Per Rule 913.a, a Form 27 workplan should be submitted for the decommissioning of the tanks that were removed. Any corrective action(s) from previous inspections that have not been addressed are still applicable See attached photos.

Location Construction

Location ID: 449275 CDP: _____

Comment: It appears that tanks have been removed from inside the engineered secondary containment. ECMC has not received a Remediation workplan for the decommissioning of this facility.

Corrective Action: Per Rule 913.a, a Form 27 workplan should be submitted for the decommissioning of the tanks that were removed.

Date: 05/16/2024

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:_____
_____Summary of Operator Response to Landowner Issues:_____
_____Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:_____
