

**State of Colorado**  
**Energy & Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

04/05/2024

Document Number:

403716104

**Off-Location Flowline**

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

**Operator Information**

ECMC Operator Number: 10459 Contact Person: James Miller  
Company Name: EXTRACTION OIL & GAS INC Phone: (720) 984-7460  
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com  
City: DENVER State: CO Zip: 80202  
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes ☒ No ☐

**OFF LOCATION FLOWLINE**

**FLOWLINE ENDPOINT LOCATION IDENTIFICATION**

Location ID: 320407 Location Type: Production Facilities  
Name: HSR-TR RANCH-62S66W Number: 3SESE  
County: ADAMS  
Qtr Qtr: SESE Section: 3 Township: 2S Range: 66W Meridian: 6  
Latitude: 39.901792 Longitude: -104.754908

**Description of Corrosion Protection**

Extraction's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, Extraction will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. Extraction retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

**Description of Integrity Management Program**

Extraction's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, Extraction ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 460509 Flowline Type: Wellhead Line Action Type: Out of Service

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 320407 Location Type: Well Site ☐   
Name: HSR-TR RANCH-62S66W Number: 3SESE   
County: ADAMS No Location ID   
Qtr Qtr: SESE Section: 3 Township: 2S Range: 66W Meridian: 6   
Latitude: 39.901792 Longitude: -104.754908

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.500   
Bedding Material: Native Materials Date Construction Completed: 07/10/1994   
Maximum Anticipated Operating Pressure (PSI): 198 Testing PSI: 198   
Test Date: 03/29/2018

**OFF LOCATION FLOWLINE Out of Service**

Date: 11/23/2020

☒ Entire Line Removal☐ Partial Line Removal**Description of Out of Service:**

The flowline servicing the HSR TR Ranch 16-3 (05-001-09237) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 4/17/2019.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 460510 Flowline Type: Wellhead Line Action Type: Out of Service

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 320433 Location Type: Well Site ☐   
Name: HSR-TR RANCH-62S66W Number: 3NWSE   
County: ADAMS No Location ID   
Qtr Qtr: NWSE Section: 3 Township: 2S Range: 66W Meridian: 6   
Latitude: 39.905186 Longitude: -104.760047

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.500   
Bedding Material: Native Materials Date Construction Completed: 03/04/1995   
Maximum Anticipated Operating Pressure (PSI): 198 Testing PSI: 198   
Test Date: 03/29/2018

**OFF LOCATION FLOWLINE Out of Service**Date: 11/23/2020☒ Entire Line Removal☐ Partial Line  
Removal**Description of Out of Service:**

The flowline servicing the HSR TR Ranch 10-3 (05-001-09307) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 4/17/2019.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments

Form 44 filed to report STATUS CHANGE notification. The following flowline(s) are now out of service:  
00109307FL: services the HSR TR Ranch 10-3 (05-001-09307)  
00109237FL: services the HSR TR Ranch 16-3 (05-001-09237)

Updated GIS data attached.  
Pressure test(s) attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 04/05/2024 Email: flowlines@civiresources.comPrint Name: Stephany OlsenTitle: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_

**Director of ECMC**Date: 5/2/2024

## CONDITIONS OF APPROVAL, IF ANY LIST

COA Type

Description

--	--

### ATTACHMENT LIST

Att Doc Num

Name

403716104	Form44 Submitted
403735807	PRESSURE TEST
403735808	PRESSURE TEST
403744430	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 4 Files

### General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)