

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2024

Submitted Date:

05/02/2024

Document Number:

698602003

FIELD INSPECTION FORM

Loc ID 338162 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10536
Name of Operator: SMITH ENERGY LLC
Address: 1540 MAIN ST SUITE 218 #334
City: WINDSOR State: CO Zip: 80550

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Chris	970-330-7034	smithenergy@live.com	
Smith, Glenn	970-330-7034	gsmithten@what-wire.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293288	WELL	PR	12/13/2007	GW	125-11040	MONK 4-18	PR

General Comment:

Inspector is completing Follow-up inspection as required by FIR. Follow-up inspection will ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 11/17/2023 FIR document number 698601289.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign is on ground.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign label is peeling and needs to be replaced.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment:
 Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Fencing around wellhead laying around well on the ground at time of inspection.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas meter is over due calibration. CORRECTIVE ACTION COMPLETED.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 293288 Type: WELL API Number: 125-11040 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698602021	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6534200