

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2024

Submitted Date:

04/26/2024

Document Number:

708903624

FIELD INSPECTION FORMLoc ID 427746 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

29 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427730	WELL	PR	10/21/2013	GW	045-21329	FEDERAL 22-13B(PH21)	PR
427731	WELL	PR	12/04/2013	GW	045-21330	Federal 21-2B (PH-21)	PR
427733	WELL	PR	12/04/2013	GW	045-21331	Federal 21-1C (PH-21)	PR
427734	WELL	PR	10/21/2013	GW	045-21332	Federal 22-12A (PH-21)	PR
427736	WELL	PR	10/24/2013	GW	045-21333	Federal 22-12D (PH-21)	PR
427739	WELL	PR	10/21/2013	GW	045-21334	Federal 21-8C (PH-21)	PR
427742	WELL	PR	10/21/2013	GW	045-21335	FEDERAL 21-8A (PH21)	PR
427744	WELL	PR	12/16/2013	GW	045-21336	FEDERAL 21-2A(PH21)	PR
427754	WELL	PR	10/21/2013	GW	045-21337	FEDERAL 21-9B(PH21)	PR
427757	WELL	PR	10/21/2013	GW	045-21338	FEDERAL 22-5C(PH21)	PR

General Comment:

CECMC Inspection Report Summary

On 04/24/2024 at approximately 13:12 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at CAERUS PICEANCE LLC Federal 22-14 (PH-21) Pad.

Location # 427746 in Garfield County Colorado.

Please refer to inspection 707800566 conducted on 08/24/2023, previous corrective action has been completed.

Location is within High Priority/Density/Black Bear Habitat areas.

Location is within Rule 411a Surface Water External Buffer.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife with a CA date of 05/03/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label on one production tank contains inaccurate information - please refer to photo log		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-2615	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	LOCATION		
Comment:	Barbed wire fence		

Corrective Action:		Date:	
Equipment:		corrective date	
Type: Gas Meter Run	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife			
Corrective Action: Comply with CECMC wildlife rules		Date: 05/03/2024	
Type: Gas Meter Run	# 1		
Comment: Summit Midstream			
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment: Pressure transducers located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment: All wells on plunger lift			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLS	STEEL AST		,
Comment: Tanks equipped with telemetry					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient			
Comment:	Tank containment damaged/buckling - please refer to photo log				
	Centralized containment				
Corrective Action:				Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID:	427730	Type:	WELL	API Number: 045-21329 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	427731	Type:	WELL	API Number: 045-21330 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	427733	Type:	WELL	API Number: 045-21331 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	427734	Type:	WELL	API Number: 045-21332 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	427736	Type:	WELL	API Number: 045-21333 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	427739	Type:	WELL	API Number: 045-21334 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	427742	Type:	WELL	API Number: 045-21335 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	427744	Type:	WELL	API Number: 045-21336 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	427754	Type:	WELL
API Number:	045-21337	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	427757	Type:	WELL
API Number:	045-21338	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
Ditches						
		Compaction				Light compaction in some areas
Compaction						Light compaction in some areas
Berms						
Rip Rap						
Gravel						Sparse to none in areas
		Gravel				Sparse to none in sections

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment for observed compliance issue	smelserw	04/25/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403770875	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6525800
708903628	Inspection 708903624 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6525797
708903629	Inspection 708903624 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6525798