

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401951108

Date Received:

02/26/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 26580

Name of Operator: BURLINGTON RESOURCES OIL & GAS LP

Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX Zip: 77079

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Liang Yu

Phone

8324866014

Email

liang.yu@cop.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 674902469

Inspection Date: 02/01/2019

FIR Submit Date: 02/14/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BURLINGTON RESOURCES OIL & GAS LP

Company Number: 26580

Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 453244

Location Name: Cottonwood Creek Number: 4-65 27-28 County: _____

Qtrqtr: SWSE Sec: 27 Twp: 4S Range: 65W Meridian: 6

Latitude: 39.668572 Longitude: -104.645950

FACILITY - API Number: 05-005- -00 Facility ID: 453244

Facility Name: Cottonwood Creek Number: 4-65 27-28

Qtrqtr: SWSE Sec: 27 Twp: 4S Range: 65W Meridian: 6

Latitude: 39.668572 Longitude: -104.645950

CORRECTIVE ACTIONS:

1 CA# 122514

Corrective Action: Reclaim all areas not needed for production. There may be room at the center of the location and the northwest of the location. Interim reclamation should have been completed by 2/1/2018.

Date: 02/01/2019

Response: CA COMPLETED

Date of Completion: 02/21/2019

Operator Comment: The room at the center of the location and the northwest of the location is reserved as the reasons below:
1) Space for truck rounting
2) Space for workover rig
3) Space for future artificial lift equipment
4) To reclaim these areas it would unearth the flowlines.

ECMC Decision: _____

ECMC
Representative: _____

2 CA# 122515

Corrective Action: Perform erosion repairs. Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Install or repair required BMPs per Rule 1002.f.

Date: 02/01/2019

Response: CA COMPLETED

Date of Completion: 02/21/2019

Operator
Comment: Repaired BMPs per Rule 1002.f. Please see attached photos.

ECMC Decision: _____

ECMC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Liang Yu

Signed: _____

Title: Sr Regulatory Coordinator

Date: 2/26/2019 1:03:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401951108	FIR RESOLUTION SUBMITTED
401951109	Post BMP Repair Photo

Total Attach: 2 Files