

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403362012

Date Received:

03/31/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

ERIN JOSEPH

970-515-1169

cogccinspections@oxy.com

AUSTIN LEE

AUSTIN.LEE@OXY.COM

ECMC INSPECTION SUMMARY:

FIR Document Number: 708000210

Inspection Date: 10/07/2022

FIR Submit Date: 01/31/2023

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 329678

Location Name: UPRC-63N65W Number: 33NWSW County: _____

Qtrqtr: NWS Sec: 33 Twp: 3N Range: 65W Meridian: 6

Latitude: 40.179907 Longitude: -104.675807

FACILITY - API Number: 05-123-00 Facility ID: 329678

Facility Name: UPRC-63N65W Number: 33NWSW

Qtrqtr: NWS Sec: 33 Twp: 3N Range: 65W Meridian: 6

Latitude: 40.179907 Longitude: -104.675807

CORRECTIVE ACTIONS:

1 CA# 167569

Corrective Action: Comply with Rule 1004. Refer to "Comment" under "COGCC Comments section" at the end of this inspection report for Corrective Action date details. Collaborate with the landowner to allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production.

Date: 05/15/2023

Response: CA COMPLETED

Date of Completion: 03/31/2023

SEE ATTACHED PHOTOS

Date: 05/15/2023

Date of Completion: 03/31/2023

Well and associated flowline corridor were reclaimed in 2018 following plugging and abandonment. The well footprint had been re-incorporated to agriculture. The flowline corridor sits in a corner outside of the associated irrigation pivot. The facility remains and services TA'd UPRC 33-11J5. OXY continues to monitor the applicable wells by drone annually.

Title: REGULATORY CONSULTANT Date: 3/31/2023 12:34:24 PM

<u>Document Number</u>	<u>Description</u>
403362012	FIR RESOLUTION SUBMITTED
403362017	AERIAL PHOTO

Page 2 of 2