

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402556190

Date Received:

12/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

cogcc.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 699700222

Inspection Date: 11/04/2020

FIR Submit Date: 12/11/2020

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335928

Location Name: SG Number: E34 496 County: _____

Qtrqtr: SWN Sec: 34 Twp: 4S Range: 96W Meridian: 6
W

Latitude: 39.660280 Longitude: -108.160547

FACILITY - API Number: 05-045- -00 Facility ID: 335928

Facility Name: SG Number: E34 496

Qtrqtr: SWN Sec: 34 Twp: 4S Range: 96W Meridian: 6
W

Latitude: 39.660280 Longitude: -108.160547

CORRECTIVE ACTIONS:

1 CA# 145067

Corrective Action: Properly dispose of oily waste in accordance with 907.e.

Date: 12/25/2020

Response: CA COMPLETED

Date of Completion: 12/14/2020

Operator Comment: Oily waste was cleaned.

ECMC Decision: _____

ECMC
Representative:

2 CA# 145068

Corrective Action: For unused , unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.

Date: 12/14/2020

Response: CA COMPLETED

Date of Completion: 12/14/2020

Operator
Comment: Riser was removed.

ECMC Decision:

ECMC
Representative:

3 CA# 145069

Corrective Action: Comply with Rule 603.f.

Date: 12/26/2020

Response: CA COMPLETED

Date of Completion: 12/14/2020

Operator
Comment: Equipment was removed.

ECMC Decision:

ECMC
Representative:

4 CA# 145070

Corrective Action: Install sign to comply with Rule 210.b.

Date: 01/11/2021

Response: CA COMPLETED

Date of Completion: 12/04/2020

Operator
Comment: One well P&A'd, the other sign was replaced.

ECMC Decision:

ECMC
Representative:

5 CA# 145071

Corrective Action: Comply with Rule 603.f .

Date: 12/26/2020

Response: CA COMPLETED

Date of Completion: 12/14/2020

Operator
Comment: Debris was removed.

ECMC Decision:

ECMC
Representative:

6 CA# 145072

Corrective Action: All foreign materials other than cuttings shall be removed from cuttings disposal area.
Land Treatment of oily waste shall be performed in strict accordance with the
requirements of COGCC Rule 907.e.(2).

Date: _____

Response: CA COMPLETED

Date of Completion: 12/14/2020

Operator
Comment:

Trash was removed.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 12/17/2020 11:19:17 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------------|
| 402556190 | FIR RESOLUTION SUBMITTED |
| 402556209 | Well P&A'd |
| 402556210 | Well Sign Added |
| 402556212 | flowline cut/capped |

Total Attach: 4 Files