

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402666340

Date Received:

04/21/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 690102340

Inspection Date: 03/17/2021

FIR Submit Date: 03/22/2021

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335610

Location Name: KIEFER GEORGE W UT B-61N67W Number: 14SWSE County: _____

Qtrqtr: SWSE Sec: 14 Twp: 1N Range: 67W Meridian: 6

Latitude: 40.045473 Longitude: -104.855309

FACILITY - API Number: 05-123-00 Facility ID: 479618

Facility Name: KIEFER GEORGE W UT B #1A Number: _____

Qtrqtr: SWSE Sec: 14 Twp: 1N Range: 67W Meridian: 6

Latitude: 40.045473 Longitude: -104.855309

CORRECTIVE ACTIONS:

1 CA# 147755

Corrective Action:

Date: 04/23/2021

Provide information requested below to COGCC Integrity Inspector (via email) and add to Corrective Actions section of COGCC supplemental form 19 spill report (pertaining to compliance of COGCC series 1100 flowline regulations):

- 1) Outline root cause of failure resulting in spill (1104.k. Integrity Failure Investigation/ operator determination)
- 2) Measures taken to prevent a recurrence of failure (1102.I Corrosion Control)
- 3) Description of flowline repair/replacement work completed (1102.j. Repair)
- 4) Perform flowline pressure testing to verify integrity of repairs/ reconnections completed prior to returning well to service (1102.j.4 and 1102.O). Contact COGCC Integrity Inspector with schedule of repair work and pressure testing. Upload flowline pressure testing chart/ data to COGCC Form 19 subsequent.

Response: CA COMPLETED

Date of Completion: 04/20/2021

Operator
Comment:

Supplemental Spill/Release Report #402664788 has been submitted to COGCC.

ECMC Decision: **Not Approved**

ECMC
Representative:

Corrective Actions have not been completed; no information entered in CA section of supplemental form 19 doc #402664788 submitted on 04/20/2021. In addition, no information communicated to COGCC Integrity Inspector regarding CA's.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 4/21/2021 11:00:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402666340	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files