

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402997975

Date Received:

03/29/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 689807072

Inspection Date: 02/07/2022

FIR Submit Date: 02/09/2022

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 324591

Location Name: DWINELL-610N79W Number: 23NESW County: JACKSON

Qtrqtr: NESW Sec: 23 Twp: 10N Range: 79W Meridian: 6

Latitude: 40.821920 Longitude: -106.232630

FACILITY - API Number: 05-057- -00 Facility ID: 212077

Facility Name: DWINELL Number: 1

Qtrqtr: NESW Sec: 23 Twp: 10N Range: 79W Meridian: 6

Latitude: 40.821920 Longitude: -106.232630

CORRECTIVE ACTIONS:

1 CA# 159612

Corrective Action: Comply with Rule 606.
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.
Properly dispose of oily waste in accordance with 905.e.

Date: 02/23/2022

Response: CA COMPLETED

Date of Completion: 03/22/2022

Operator Comment: Unused tank has been removed from location.

ECMC Decision: _____

ECMC
Representative:

2 CA# 159613

Corrective Action: Comply with Rule 606.

Date: 03/09/2022

Response: CA COMPLETED

Date of Completion: 03/22/2022

Operator
Comment:

Broken load line bucket was a cause of overflowing and stained soil. It was replaced. Please see attached pictures.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering Tech

Date: 3/29/2022 1:27:58 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402997975	FIR RESOLUTION SUBMITTED
402998001	Replaced bucket PIC

Total Attach: 2 Files