

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403573071

Date Received:
10/26/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

7 of 8 CAs from the FIR responded to on this Form

7 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Mollie O'hare	9705634000	mollieo@maralexinc.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 700300669
Inspection Date: 08/29/2023 FIR Submit Date: 09/05/2023 FIR Status:

Inspected Operator Information:

Company Name: MARALEX RESOURCES INC Company Number: 53255
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

LOCATION - Location ID: 306805

Location Name: Mollie Corynne 33-7-2 Number: 3C County: LA PLATA
Qtrqtr: NENE Sec: 2 Twp: 33N Range: 7W Meridian: N
Latitude: 37.137217 Longitude: -107.571556

FACILITY - API Number: 05-067- -00 Facility ID: 440997

Facility Name: Mollie Corynne 33-7-2 Number: 3C
Qtrqtr: NENE Sec: 2 Twp: 33N Range: 7W Meridian: N
Latitude: 37.137217 Longitude: -107.571556

CORRECTIVE ACTIONS:

1 CA# 180228

Corrective Action: Install secondary containment Date:

Response: CA COMPLETED Date of Completion: 09/06/2023

Operator Comment: Tanks were bermed during drilling operations. Location was bermed. Please see attached photos. Prior to 10/25/2023 Tanks were removed from the location.

ECMC Decision:

ECMC
Representative:

2 CA# 180229

Corrective Action: nspect, repair, maintain and paint (for condition, not visual impact) tanks and valves per Rule 609, 608.e and 608.g and 1002.f.
Provide written spill contingency plan required by 608.g for all tanks including temporary tanks as FIRR
Submit FIRR per Rule 210.b

Date: 07/21/2023

Response: CA COMPLETED

Date of Completion: 10/25/2023

Operator Comment: Tanks are used for drilling purposes only. Tanks are rented by drilling company from a third party. Maralex was informed by the third party who owns the tanks that they were repaired and the ground is almost dry around the tank. Water in the tank is drinking water and not a threat to the health, safety, welfare or environment. See attached water analysis. Tanks have been bermed. Spill report will reflect this. Spill report document number 403509665.

ECMC Decision: _____

ECMC
Representative:

3 CA# 180230

Corrective Action: Stop leaks, clean up free fluids, file spill report

Date: 08/24/2023

Response: CA COMPLETED

Date of Completion: 08/28/2023

Operator Comment: Maralex was informed by the third party who owns the tanks that they were repaired and the ground is almost dry around the tank. Water in the tank is drinking water and not a threat to the health, welfare or environment. See attached water analysis. Spill report filed. Document #403509665. Tanks were removed prior to 10/25/2023.

ECMC Decision: _____

ECMC
Representative:

5 CA# 180232

Corrective Action: clean up impacted material at wellhead of 067-08800

Date: 06/07/2023

Response: CA COMPLETED

Date of Completion: 09/05/2023

Operator Comment: Stuffing box leak was repaired. Soiled gravel removed and new gravel added. Several buckets of contaminated dirt were removed from around the wellhead. Pictures attached. Clean gravel was brought in to replace the soiled gravel.

ECMC Decision: _____

ECMC
Representative:

6 CA# 180233

Corrective Action: Fully comply with Rule 605.a by having calls returned by someone with knowledge of operations and operational authority.

Date: _____

Response: CA COMPLETED

Date of Completion: 08/24/2023

Operator Comment: Staff has been informed to communicate the urgency of returning calls.

ECMC Decision: _____

ECMC
Representative:

7 CA# 180234

Corrective Action: perform and submit annual bradenhead test per Rules 419 and 420

Date: _____

Response: CA COMPLETED

Date of Completion: 10/26/2023

Operator
Comment:

The well was temporarily abandoned for drilling operations. Annual bradenhead test completed 10/26/2023

ECMC Decision: _____

ECMC
Representative:

8 CA# 180235

Corrective Action: Install vehicle tracking pad or equivalent BMPs and stop tracking onto county road. Train crews and empty spill response measures to prevent any fluids migrating off site and chemical and material handling BMPs to prevent mixing of chemicals, materials and refined wastes such as motor oil, glycol and hydraulic fluid or impacting surface materials per Rule 1002.f

Date: _____

Install BMPs on portable toilets (staking down units and having adequate spill response on

Response: CA COMPLETED

Date of Completion: 10/25/2023

Operator
Comment:

The forecasted weather is sunny and dry for the remainder of the estimated drilling operations. Vehicle tracking pads are not necessary for this operation. Spill response measures have been enacted. Berms have been repaired and sump pump has been repaired and at full capacity. Absorbent pads, dirt and rags are located on the site for use if refined waste or fresh water spills occur. Portable toilets have been secured as per the BMPs for the vendor. As of today, drilling has ceased and location is in the process of being returned to normal operations.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mollie O'Hare

Signed: _____

Title: EA

Date: 10/26/2023 2:40:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403573071	FIR RESOLUTION SUBMITTED
403573081	Photo

403573082

photo

Total Attach: 3 Files