

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403676163

Date Received:

02/04/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 17210

Name of Operator: CINNAMON CREEK OIL & GAS INC

Address: P O BOX 544

City: WALSH State: CO Zip: 81090

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mills, Rick

719-324-5630/719-353-2523

rickmills000@gmail.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 695109083

Inspection Date: 01/26/2024

FIR Submit Date: 01/26/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CINNAMON CREEK OIL & GAS INC

Company Number: 17210

Address: P O BOX 544

City: WALSH State: CO Zip: 81090

LOCATION - Location ID: 322268

Location Name: JOHNSON & STOCKER-
619S70W

Number: 2SWNE

County: FREMONT

Qtrqr: SWNE Sec: 2 Twp: 19S Range: 70W Meridian: 6

Latitude: 38.426080 Longitude: -105.190060

FACILITY - API Number: 05-043-00

Facility ID: 210091

Facility Name: JOHNSON & STOCKER

Number: 1

Qtrqr: SWNE Sec: 2 Twp: 19S Range: 70W Meridian: 6

Latitude: 38.426080 Longitude: -105.190060

CORRECTIVE ACTIONS:

1 CA# 191463

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS THE SECOND NOTICE, IMMEDIATE ACTION IS REQUIRED.

Date: _____

Response: CA COMPLETED

Date of Completion: 01/30/2024

Operator
Comment:

Operator is seeking variance to exempt the Johnson Stocker well from bradenhead testing. This well was drilled during the turn of the century, approximately 1920, and was cased from surface to setting depths with clamps or welding, and did not have bradenhead access on the wellhead. Casing, on historical wells such as these, cannot be modified without compromising the integrity of the steel. Hot-tapping a 2" opening to plumb access fittings compromises the casing and can result in splits or micro-fissures, which in turn, requires pulling and damaging

the well. These 100+ year wells produce in paying quantites and have declined to producing rates of 1-2 bbls per week. Pressure on these wells is too small to measure and have no migrating gas to surface.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This FIRR advises that Operator is seeking a variance to bradenhead testing on the Johnson Stocker well, a turn of the century completion (1920), with wellbore construction consisting of casing strings clamped or welded on without bradenhead access. Operator is concerned about hot-tapping an access into the casing and potentially damaging the casing which would in turn compromise the well integrity. At this time, there is no measurable pressure or observation of fugitive gas from the well, indicating the casing is securely isolating hydrocarbon migration.

See "Attachments" tab for correspondance to the STATE requesting further discussion on bradenhead test issues on historical wells. A recent phone conversation between the Operator and Engineering Supervisor and Engineer concluded that a variance should be submitted. Operator is currently engaging a third party to prepare a variance.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rick Mills

Signed: _____

Title: Owner

Date: 2/4/2024 6:49:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403676163	FIR RESOLUTION SUBMITTED
403676168	Wellbore diagram
403676169	Correspondance with State Engineering group

Total Attach: 3 Files