

Inspection Photos

Location Name: TEP Rocky Mountain LLC NORCROSS A Pad

Location # 335544



Photo # 5308 From entrance to location




Photo # 5309 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC NORCROSS A Pad

Location # 335544



Photo # 5310 Location



Photo # 5311 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC NORCROSS A Pad

Location # 335544



Photo # 5312 Location



Photo # 5313 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC NORCROSS A Pad

Location # 335544



Photo # 5314 Location



Photo # 5315 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC NORCROSS A Pad

Location # 335544



Photo # 5316 PRV vent line does not comply with CECMC pressure safety device rules & general safety rules



Photo # 5317 PRV vent line does not comply with CECMC pressure safety device rules & general safety rules