

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2024

Submitted Date:

04/29/2024

Document Number:

714300060

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Brown, Kari 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
,		cogcc@kpk.com	
Anderson, Laurel		laurel.anderson@state.co.us	
Peterson, John		jpeter@kpk.com	KPK environmental
Watzman, Ross	303-825-4822	rwatzman@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485940	SPILL OR RELEASE	AC			-	Facility 4 @ UPRR 43 PAN AM AE	EI

General Comment:

This is a follow up inspection to document no 710100195 for Spill ID 485940 to determine the status of fencing at this spill location. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	Fencing at this location remains inadequate; installed fencing does not prevent access to the open excavation. Spill location is directly adjacent to a neighborhood.		
Corrective Action:	Per CA on FIR Doc #710100170 & 710100195: "Operator shall implement, continuously monitor and maintain best management practices to protect the environment, public health, safety and welfare and the environment as required by Rule 913.b.(5)B.i and ECMC Guidance 913.b. (5)B i-v which requires fencing used be appropriate to site conditions, ie: nearby residences, depth of excavation, presence of ground or surface water, livestock, wind, etc. when sites are not attended."		Date: 04/25/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 485940 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403773235	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528886
714300061	Site Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528876