

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2024

Submitted Date:

05/06/2024

Document Number:

708903700

FIELD INSPECTION FORM

Loc ID 323796 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210831	WELL	PR	09/12/1989	GW	045-06589	DOE 1-W-32	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 05/02/2024 at approximately 15:41 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC DOE 1-W-32 Pad. Location # 323796 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas. Location is approximately 5 yards from a drainage that contributes to the Colorado River. While there, I observed normal production operations.

[This is a summary of inspection report.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Type	OTHER		
Comment:	Meter house		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:
Type	OTHER		
Comment:	Meter house - hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 2		
Comment:	Marked		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	Well not on plunger lift		
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210831 Type: WELL API Number: 045-06589 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well is not on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Compaction				
Ditches						
		Gravel				Sparse to none in sections
Rip Rap						
		Tracking Pad				Aggregate/gravel based VTC
Gravel						Sparse to none in areas
		Ditches				
Check Dams						
Berms						
Compaction						Light compaction in small areas

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903701	Inspection 708903700 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6536879
708903702	Inspection 708903700 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6536880