

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2024

Submitted Date:

05/06/2024

Document Number:

708903706

FIELD INSPECTION FORM

Loc ID 324108 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257370	WELL	PR	05/15/2000	GW	045-07551	FEDERAL PA 22-32	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 05/02/2024 at approximately 15:57 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FEDERAL PA 22-32 Pad. Location # 324108 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas. Location is approximately 77 yards from a drainage that contributes to the Colorado River. While there, I observed normal production operations.

[This is a summary of inspection report.](#)

Location

Lease Road:			
	Type Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
	Type OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:			Date:
	Type SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pip rail fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 257370 Type: WELL API Number: 045-07551 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none in sections
Compaction						Small areas of light compaction
Ditches						
Rip Rap						
				Material Handling And Spill Prevention		Chemical tank containment
Sediment Traps						
Berms						
		Ditches				
Gravel						Sparse to none in most areas
		Tracking Pad				Aggregate/gravel based VTC
		Culverts				
		Compaction				

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Aggregate/gravel based VTC at intersection of public road & start of lease road. Dimensions & details are as follows - approximately 75 ft long, 27 ft wide & varying depths from 1-3 inches, depth insufficient, area does not appear to have been excavated & no class 2 geotextile fabric observed.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903707	Inspection 708903706 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6536978
708903708	Inspection 708903706 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6536979