

Inspection Photos  
Location Name: Brecken LD28-747 Production Facility  
Location ID: 441926



Energy and Carbon Management Commission  
40.71506, -103.86676, 4790.4ft  
04/30/2024 12:47:19



Energy and Carbon Management Commission  
40.71541, -103.86745, 4785.7ft  
04/30/2024 12:47:59

Photo 1 – Signs at Entrance

Photo 2 – Maintenance Tank

**Inspection Photos**  
**Location Name: Brecken LD28-747 Production Facility**  
**Location ID: 441926**



**Photo 3 – Gas Meters**



**Photo 4 – Compressor**

**Inspection Photos**  
**Location Name: Brecken LD28-747 Production Facility**  
**Location ID: 441926**



**Photo 5 – Compressor**

**Photo 6 – LACT**

**Inspection Photos**  
**Location Name: Brecken LD28-747 Production Facility**  
**Location ID: 441926**



Energy and Carbon Management Commission  
40 71596 -103.86719, 4806 6ft  
04/30/2024 12:49:18



Energy and Carbon Management Commission  
40 71604 -103.86758, 4781 9ft  
04/30/2024 12:50:30

**Photo 7 – Compressor Drain Vault – Stained Soil**

**Photo 8 – Separators**

**Inspection Photos**  
**Location Name: Brecken LD28-747 Production Facility**  
**Location ID: 441926**



**Photo 9 – Production Equipment**

**Photo 10 – Separators**

**Inspection Photos**  
**Location Name: Brecken LD28-747 Production Facility**  
**Location ID: 441926**



**Photo 11 – Tank Battery**

**Photo 12 – LACT**

**Inspection Photos**  
**Location Name: Brecken LD28-747 Production Facility**  
**Location ID: 441926**



**Photo 13 – Water Tanks**

**Photo 14 – ECDs**

**Inspection Photos**  
**Location Name: Brecken LD28-747 Production Facility**  
**Location ID: 441926**



**Photo 15 – VRU**

**Photo 16 – VRTs**

## Inspection Photos

Location Name: Brecken LD28-747 Production Facility

Location ID: 441926



**Photo 17 – Separators**