

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead

1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 217855 Type: WELL API Number: 071-06634 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/04/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input style="width:100%;" type="text"/> Corrective Action: <input style="width:100%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: <u>119944</u>	Lat: <u>37.103735</u>	Long: <u>-104.760919</u>		
Reference Point: _____	Other: _____	Length: _____	Width: _____			
Lining:						
Liner Type: _____			Liner Condition: _____			
Comment: <input style="width:100%;" type="text"/> Corrective Action: <input style="width:100%;" type="text"/>						Date: _____
Fencing:						
Fencing Type: <u>None</u>			Fencing Condition: _____			
Comment: <input style="width:100%;" type="text"/> Corrective Action: <input style="width:100%;" type="text"/>						Date: _____
Netting:						
Netting Type: _____			Netting Condition: _____			
Comment: <input style="width:100%;" type="text"/> Corrective Action: <input style="width:100%;" type="text"/>						Date: _____
Anchor Trench Present: <u>NO</u>		Oil Accumulation: <u>NO</u>		2+ feet Freeboard: <u>YES</u>		
Comment: <input style="width:100%;" type="text"/> Corrective Action: <input style="width:100%;" type="text"/>						Date: _____

ECMC Comments		
Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695107904, CA HAS BEEN ADDRESS. FIRR WAS NOT REPORTED, IT IS REQUIRED IN THE NEW RULES FOR FIRR'S TO BE SUBMITTED AS SOON AS CORRECTIVE ACTIONS ARE ADDRESSED, OPERATOR MUST SUBMIT 1 FIRR (PREFERABLE WITH PHOTOS) FOR EVERY INSPECTION THAT HAS CORRECTIVE ACTION. BE SURE TO ONLY SUBMIT1 FIRR PER INSPECTION THAT ADDRESSES ALL CA'S LIST ON THE ORIGINAL FIR (INSPECTION).	beardslt	04/22/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695109507	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6537049