

# Interim Reclamation and Stormwater Inspection

Date: 05/03/2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 332971

Inspection Document #: 708201230

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 1.** Russian Olive (CO List B Noxious Weed) observed growing on the southwest portion of the interim areas.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 2.** Undesirable vegetation (kochia) growing throughout the tank battery secondary containment.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 3.** Close up example of hoary cress (CO List B Noxious Weed) growing throughout the location. Note - hoary cress was observed throughout the interim areas, western area pictured.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 4.** Weed debris observed throughout the location and equipment, separator pictured.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 5 & 6.** Open excavation with exposed flowlines. During this inspection, it was observed that the taped flowline was dripping with an unknown fluid with a discolored area directly underneath the flowline. Undesirable vegetation (curly dock) and older weed debris was observed within the open excavation.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 7.** Production areas are predominantly undesirable vegetation (kochia).

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 8 , 9 & 10.** Stockpiled material from the open excavation does not have adequate secondary containment or proper stormwater control measures/BMPs to prevent stormwater from commingling with impacted materials and discharging off location into adjacent areas. Liner is deteriorating and not adequate.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 11.** Equipment (e.g. trailers, tanks, etc) not needed for production operations is being stored on location.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 12 & 13.** Secondary containment/berms around tank battery facility is not adequate as evidenced by unconsolidated materials and damage to berms (right photo, red arrow). Debris, trash and undesirable vegetation (kochia) also observed throughout.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 14 & 15.** Buried produced water vault does not have adequate wildlife exclusion devices installed at openings.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 16 & 17.** Fiberglass tank does not have adequate wildlife exclusion devices installed at openings.

Inspection Photos  
Location Name: Hladky O’Gorman #3  
Location ID: 332971



**Photo 18.** Tank battery does not have adequate wildlife exclusion devices installed at openings.



**Photo 19.** Free fluids observed within loadout line collection bucket need to be properly cleaned and disposed of.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 20.** Trash and debris observed around wellhead.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 21.** Weed debris observed throughout production equipment (electrical panels).

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 22 & 23.** Undesirable vegetation (curly dock) and CO List B Noxious Weed (canada thistle) growing within cattle guard.

Inspection Photos  
Location Name: Hladky O'Gorman #3  
Location ID: 332971



**Photo 24.** Undesirable vegetation (kochia) growing within the production areas.