

Inspection Photos

May 2nd, 2024

Operator: Maralex Resource Inc. - 53255

Location ID: 333984

Inspection Document #: 714000732

La Plata County, CO

Township: NWSW 14 33N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Artfgance 33-7-14 2A, 3C
Location ID: 333984

5/2/24
+37.103779,-107.582791
202° S



Photo 1. View of the well disturbance from the access point facing center.

Inspection Photos
Location Name: Artfgance 33-7-14 2A, 3C
Location ID: 333984

5/2/24
+37.103820,-107.582670
168° S



Inspection Photos

Location Name: Artfgance 33-7-14 2A, 3C

Location ID: 333984




Photo 3. Produced water tanks on location are in use but are not marked.

Inspection Photos

Location Name: Artfgance 33-7-14 2A, 3C

Location ID: 333984



Photo 4. View of plastic tubing trash and unused oil and gas equipment on location.

Inspection Photos

Location Name: Artfgance 33-7-14 2A, 3C

Location ID: 333984



Photo 5. View of rutting observed on the active pad. Additional stabilization is needed to minimize site degradation.

Inspection Photos

Location Name: Artfgance 33-7-14 2A, 3C

Location ID: 333984



Photo 6. Impacted surface material observed at the 2A well head.



Inspection Photos

Location Name: Artfgance 33-7-14 2A, 3C

Location ID: 333984



Photo 7. View of impacted surface material at both lube oil tanks secondary containments at both pump jacks.

Inspection Photos
Location Name: Artfgance 33-7-14 2A, 3C
Location ID: 333984



Photo 8. Musk thistle observed on the active pad.