

# Inspection Photos

May 2nd, 2024

Operator: Maralex Resources Inc - 53255

Location ID: 311958

Inspection Document #: 714000742

La Plata County, CO

Township: SWSE 3 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Mary Catherine 33-7-3 2A, 3C  
Location ID: 311958



5/2/24  
+37.128938,-107.592164  
292° W



**Photo 1.** View of the well disturbance taken from the entrance facing center.



## Inspection Photos

Location Name: Mary Catherine 33-7-3 2A, 3C

Location ID: 311958



**Photo 2.** Impacted surface material remains at both well heads.



# Inspection Photos

Location Name: Mary Catherine 33-7-3 2A, 3C

Location ID: 311958



**Photo 3.** Failing storm water BMPs observed in the western interim reclamation area, maintenance is required.



Inspection Photos

Location Name: Mary Catherine 33-7-3 2A, 3C

Location ID: 311958

5/2/24

+37.129192,-107.592631

59° NE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of the northern interim reclamation area facing north east.  
Vegetation comprised of indian rice grass and rabbit brush.

API #: 067-09049, 09476



Inspection Photos  
Location Name: Mary Catherine 33-7-3 2A, 3C  
Location ID: 311958



**Photo 5.** Reference area comprised of indian rice grass, sage brush, juniper and antelope bitterbrush.