

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 311-5 Pad

Location ID: 334725



Photo # 5819 From entrance to location



Photo # 5820 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC PA 311-5 Pad
Location ID: 334725



Photo # 5821 Location

Photo # 5822 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC PA 311-5 Pad
Location ID: 334725



Photo # 5823 Location

Photo # 5824 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 311-5 Pad

Location ID: 334725



Photo # 5825 Location



Photo # 5826 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 311-5 Pad

Location ID: 334725



Photo # 5827 Open ended load line



Photo # 5828 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 311-5 Pad

Location ID: 334725



Photo # 5829 Debris



Photo # 5830 Debris

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC PA 311-5 Pad
Location ID: 334725




Photo # 5832 Battery sign does not list all wells associated with tank battery