

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2024

Submitted Date:

05/07/2024

Document Number:

697009504

FIELD INSPECTION FORMLoc ID 332984 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297440	WELL	SI	03/01/2023	OW	123-27135	VILLAGE 16A-DU	WK

General Comment:

This is a well plugging inspection.

LocationOverall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Rig, pump, work tanks and support equipment are grounded.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 297440 Type: WELL API Number: 123-27135 Status: SI Insp. Status: WK**Cement**Cement ContractorContractor Name: Duco

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): 115 sxsGood Return During Job: YESCement Type: Class G Neat 15.8#Comment:

CIBP #2 set @ 2500' KB, EOT @ 2500' KB, MIRU Duco cementers, hold safety meeting, establish circulation, pump 10 bbls fresh water spacer, mix and pump 20 sxs Class G Neat 15.8 ppg cement slurry (4 bbls total) on top of CIBP, displace tbg with 9 bbls of fresh water, RD cementers, lay down tbg to 1580' KB, RU cementers, establish circulation, pump 10 bbls fresh water spacer, mix and pump 25 sxs Class G Neat 15.8 ppg cement slurry (5.1 bbls total) balance plug, displace tbg with 5 bbls of fresh water, RD cementers, lay down tbg to 677' KB, RU cementers, mix and pump 70 sxs Class G Neat 15.8 ppg cement slurry surface plug (14.3 bbls total) with cement returned to work tank, RD cementers, lay down remaining tbg, top off cement, RDMO cementers, SIW, RDMO.

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 02/14/2024Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697009505	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539577