

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2024

Submitted Date:

05/01/2024

Document Number:

707602622

FIELD INSPECTION FORM

Loc ID 323714 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------------------------------|---------------------------------|
| | | rbucogccinspectionreports@chevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 245611 | WELL | TA | 12/19/2019 | OW | 123-13406 | TREBOR B12-7 | TA |

General Comment:

This is a WELL / ABANDONED BATTERY inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.416800 / -104.498219

Abandoned Centralized Battery formerly served 3 Location IDs (323714, 323705, 323772).
(Well(s): 1: Temporarily Abandoned | TA ; 2: Plugged & Abandoned | PA).

| Location | | | |
|--------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|-------------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. | | |
| Corrective Action: | Comply with Rule 606.c. Corrective Action date: 05/15/2024. (14-days). See photo #2. <i>*Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</i> | | Date: <u>05/15/2024</u> |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Gas Meter Run | # 0 | | corrective date |
| Comment: | Battery Abandoned. Equipment removed. | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears plumbed to surface. | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 0 | | |
| Comment: | Temporarily Abandoned TA. Equipment removed. | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------------------|------------------------------------------|-------|--|
| Type: Horizontal Heated Separator | # 0 | | |
| Comment: | Battery Abandoned. Equipment removed. | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 0 | | |
| Comment: | Battery Abandoned. Equipment removed. | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Wellhead: w/ Master, casing valves. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|------------------------------------------|----------|------|---------|--------|
| CRUDE OIL | 0 | | | | , |
| Comment: | Battery Abandoned. Equipment removed. | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|------------------------------------------|----------|------|---------|--------|
| PRODUCED WATER | 0 | | | | , |
| Comment: | Battery Abandoned. Equipment removed. | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 245611 Type: WELL API Number: 123-13406 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
Locked-out, Tagged-out | LOTO.
Black NEWS tag posted.
CECMC records last prod: 03/2017.

Form 4 on file. TA date: 10/03/2019. Approved.
DH-CIBP set.
Form 6A on file. Out-of-Svc Designation.
Date: 03/01/2017. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 08/30/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| Reclamation - Storm Water - Pit | | | | | | |
|----------------------------------------------------------------------------------------------------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|-------------|
| Storm Water: | | | | | | |
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | Pass | | | | | |
| Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/> | | | | | | Date: _____ |
| Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT | | | | | | |

| ECMC Comments | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| Comment | User | Date |
| <p>CECMC Inspection Report Synopsis:</p> <p>On MON 04/29/2024 at approximately 16:45 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: TREBOR-65N64W/12SWNE Location ID: 323714 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.416800 / -104.498219</p> <p>During this inspection the following possible compliance issue(s) were observed: 1.) Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 05/15/2024. (14-days). See photo #2.</p> <p>*Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> | evinsb | 05/01/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 403776121 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6532318 |
| 707602623 | Site photo(s) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6532301 |