

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/16/2024

Submitted Date:

05/01/2024

Document Number:

708700054

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, SIMCOE		sjninspections@ikavenergy.co	

General Comment:

This is an Environmental inspection to document spill status. Spill reported on 4/10/2024.

Marsh area down slope from spill area appears to have been impacted by spill. This inspector observed salt stained deposits in marsh area. See attached photos. Standing water was observed in marsh.

From spill report: "An unknown volume of produced water was released from a buried 3" steel pipeline. Produced water flowed into a drainage surrounded by agricultural fields. The pipeline was isolated to stop the release. Soil and water samples were collected and results will be submitted on a supplemental Form 19."

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: Alleged Violation: Operator reported spill of produced water. This inspector observed salt staining within marsh indicating produced water spill impacted surface water.

Corrective Action: Collect soil and water samples as needed to delineate the horizontal and vertical extent of spill and impacts. Submit analytical results on a Form 19 Supplemental. Date: 05/31/2024

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: 0 Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403775669	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6531991
708700055	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6531989