

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/28/2024

Submitted Date:

05/02/2024

Document Number:

694500645

FIELD INSPECTION FORM

Loc ID: 449274 Inspector Name: NEIDEL, KRIS On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Blohm, Justin	520-820-2380	justin.blohm@fulcrumeo.com	
Penner, Annalee	417-773-2341	annalee.penner@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449275	WELL	PR	10/01/2020	OW	057-06598	REU 0681 1-23H2	EI

General Comment:

On 3/28/2024 ECMC staff, Kris Neidel inspected Rabbit Ears location. The location was mostly covered in snow and puddled water. The well was SI at the time of inspection. It appears that tanks have been removed from inside the engineered secondary containment. ECMC has not received a Remediation workplan for the decommissioning of this facility. Corrective Action: Per Rule 913.a, a Form 27 workplan should be submitted for the decommissioning of the tanks that were removed. Any corrective action(s) from previous inspections that have not been addressed are still applicable See attached photos.

Location Construction

Location ID: 449275 CDP: _____

Comment: It appears that tanks have been removed from inside the engineered secondary containment. ECMC has not received a Remediation workplan for the decommissioning of this facility.

Corrective Action: Per Rule 913.a, a Form 27 workplan should be submitted for the decommissioning of the tanks that were removed.

Date: 05/16/2024

Form 2A COAs:

Comment:

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 449275 Type: WELL API Number: 057-06598 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403777719	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6534096
694500646	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6534088