

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2024

Submitted Date:

05/09/2024

Document Number:

716300005

**FIELD INSPECTION FORM**

Loc ID 321307 Inspector Name: CANFIELD, CHRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Jacob Evans		jevans@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206632	WELL	TA	09/01/2023	OW	013-06127	ERIE 1-24	TA
485667	SPILL OR RELEASE	CL	11/21/2023		-	ERIE-61N69W 24SENW	CL

**General Comment:**

[Environmental inspection of Location ID 321307 subject to ECMC Remediation Project 31520.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Trackout control mats (as shown in the attached photo log) were installed at the entrance to the location.		
Corrective ActionL		Date:	

Overall Good:

<b>Emergency Contact Number:</b>			
Comment:	Signs were posted at the entrance to the location, however those signs did not include a 24/7 telephone number for the Operator.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type			
Comment:	Excellent housekeeping.		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:	Well maintained perimeter fence as shown in the attached photo log.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**

Facility ID: 206632 Type: WELL API Number: 013-06127 Status: TA Insp. Status: TA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485667 Type: SPILL OR API Number: - Status: CL Insp. Status: CL

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: [At the time of this inspection, the excavation had been backfilled. Top soil was being delivered and spread \(see attached photo log\).](#)

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**ECMC Comments**

Comment	User	Date
<a href="#">Environmental inspection of Location ID 321307 subject to ECMC Remediation Project 31520.</a>	canfielc	05/09/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716300007	Inspection Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6542225">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6542225</a>