

From: Priscilla Shorty <pshorty@hilcorp.com>
 Sent: Thursday, March 7, 2024 1:38 PM
 To: Francisco Enriquez Quintana <Francisco.Quintana@hilcorp.com>; Freddy Proctor <fproctor@hilcorp.com>; Jennifer Street <jstreet@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>;
 Shad Brown <shbrown@hilcorp.com>; Tammy Jones <tajones@hilcorp.com>
 Subject: ARGENTA 33-10 3 1 - INC - 714000509

Today's Date:	3/7/2024					
Well Name:	ARGENTA 33-10 3 1	Location:	Sec: 03	Twon: 033N	Rng: 010W	UL: F
API Number:	05.067.08128	Footage:	1530' FNL & 1850' FWL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	01	0101	Francisco Enriquez Quintana	
Meter #:	06633028	Pipeline:	HEC			
INC Number:	714000509	Agency:	COGCC	Inspector:	Corey McDonough	
Type of INC:	Written	Photos Required:	Yes	Due Date:	3/22/2024	
Issue of Concern:	<p>Comment: Unused oil and gas equipment observed on location. Corrective Action: Comply with rule 606. Date: 03/22/2024.</p> <p>Comment: Weedy russian thistle debris observed around the well head. Corrective Action: Comply with rule 606, remove and properly dispose of debris. Date: 03/14/2024</p> <p>Inspection doc #693902986 observed rutting on location and required compliance by 4/24/2021. It was observed in this inspection that rutting remains on location. No CA date is being provided as this location is out of compliance for the same Rule. Original CA has not been addressed. Original CA and date remains applicable. Additional gully erosion was observed forming on the western edge of the disturbance and needs to be stabilized. Corrective Action: Comply with rule 1002 Install or repair required BMPs.</p> <p>**See attached document and photos for more details**</p>					

Priscilla Shorty
 Operations Regulatory Technician
 Hilcorp Energy Company





Unused oil and gas equipment has been removed.



Weedy debris have been removed.



Rutting and erosion issues have been resolved.



Rutting and erosion issues have been resolved.