

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



May 1, 2024 at 10:35:11 AM
+40.529268,-106.404035 ±4.74r
ECM

Location



May 1, 2024 at 10:36:44 AM
+40.510245,-106.384233 ±4.74r
ECM

Location

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Location



Location

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



May 1, 2024 at 10:38:07 AM
+40.509986,-106.384023 ±4.74r
ECM

Location



May 1, 2024 at 10:37:18 AM
+40.510173,-106.384148 ±4.74r
ECM

Location

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Old signage and debris



Old signage and debris

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Old signage



Old signage and debris

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Staining



Tank battery lacking battery signage

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



May 1, 2024 at 10:39:16 AM
+40.509783,-106.384189 ±4.74r
ECM

Location



May 1, 2024 at 10:39:37 AM
+40.509654,-106.384396 ±4.74r
ECM

Location

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Staining



Debris

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Debris



Debris

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Debris



Black line safety monitor

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Staining




Staining coming from under chemical tank containment

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Staining



Staining

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Unmarked container



Unmarked container

Fulcrum
Surprise unit 0680 S9
Location ID: 445005



Location