

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/09/2024

Submitted Date:

05/09/2024

Document Number:

697009520

FIELD INSPECTION FORM

Loc ID 332984 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297443	WELL	SI	03/01/2023	OW	123-27138	VILLAGE 16N-DU	WK

General Comment:

This is a well plugging inspection.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Rig, pump, work tanks and support equipment are grounded.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 297443 Type: WELL API Number: 123-27138 Status: SI Insp. Status: WK

Cement

Cement Contractor

Contractor Name: Duco Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): 110 sxs

Good Return During Job: YES Cement Type: Class G Neat 15.8#

Comment: MIRU Ranger Energy Services e-line, hold safety meeting, RIH with CIBP #1 and set @ 7192' KB, POOH with setting tool, RIH with dumpbailer and spot 2 sxs of cement slurry on top of CIBP, POOH with dumpbailer, load and pressure test csg to 1500 psig with no leakoff, release pressure, RIH with CIBP #2 and set @ 2500' KB, POOH with setting tool, RDMO e-line, TIH with tbg to 2500' KB, MIRU Duco cementers, hold safety meeting, establish circulation, pump 10 bbls fresh water spacer, mix and pump 20 sxs Class G Neat 15.8 ppg cement slurry (4 bbls total) on top of CIBP, displace tbg with 9 bbls of fresh water, RD cementers, lay down tbg to 1585' KB, RU cementers, establish circulation, pump 10 bbls fresh water spacer, mix and pump 25 sxs Class G Neat 15.8 ppg cement slurry balance plug (5.1 bbls total), displace tbg with 5 bbls of fresh water, RD cementers, lay down tbg to 679' KB, RU cementers, mix and pump 65 sxs Class G Neat 15.8 ppg cement slurry with cement returned to work tank, RD cementers, lay down remaining tbg, top off cement, SIW, RDMO cementers, RDMO.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/14/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697009521	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6542636