


Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337




As signs are replaced additional information will be required

As signs are replaced additional information will be required

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



Weeds from last year



Liner no longer impervious to fluids

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



Open ended load line




Tank label missing required information

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



May 7, 2024 at 12:56:10 PM



May 7, 2024 at 12:56:29 PM

Tank label missing required information

Stained soil

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



Open to wildlife



Weeds from last year

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



As signs are replaced additional information will be required

As signs are replaced additional information will be required

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



Weeds from last year



Unmarked anchor

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



Debris



Debris

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



Debris



Debris. Unused equipment. Open to wildlife

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



Unused equipment



Location from Northeast corner

Hilcorp Energy Company
Duncan Vanschaick-612N100W 29SWNW
Location ID: 333337



Location from Southwest corner



Location from Southeast corner