

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal 30-12 (PL30) Pad

Location #: 414077



Photo # 6485 From entrance to location



Photo # 6486 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal 30-12 (PL30) Pad

Location #: 414077



Photo # 6487 Location



Photo # 6488 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal 30-12 (PL30) Pad

Location #: 414077



Photo # 6489 Location



Photo # 6490 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal 30-12 (PL30) Pad

Location #: 414077



Photo # 6491 Barbed wire fence needs maintenance/wildlife hazard



Photo # 6492 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal 30-12 (PL30) Pad

Location #: 414077




Photo # 6493 Barbed wire fence needs maintenance/wildlife hazard



Photo # 6494 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal 30-12 (PL30) Pad

Location #: 414077



Photo # 6495 Debris



Photo # 6496 Stained gravel in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal 30-12 (PL30) Pad

Location #: 414077



Photo # 6497 Stained gravel in secondary containment




Photo # 6498 Stained gravel in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal 30-12 (PL30) Pad

Location #: 414077



Photo # 6499 Stained gravel in secondary containment



Photo # 6500 Stained gravel in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal 30-12 (PL30) Pad

Location #: 414077



**Photo # 6501 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



**Photo # 6502 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**