

Inspection Photos

API: 011-05055

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 5/8/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 2. Facing northeast toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 3. Facing northeast at the location. There is various unused equipment, supplies and tanks stored at the location that will need to be removed.



Inspection Photos



Photo 4. Facing northwest toward the GAS PROCESSING PLANT and Wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 011-05055 | Date: 5/8/2024

Inspection Photos



Photo 5. Facing northwest at the sheds and various equipment which are in disrepair. There is chemical barrels with no containment and various debris laying on the ground.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-05055 | Date: 5/8/2024

Inspection Photos



Photo 6&7. There are other sheds with large bird nests. Operator will need to consult with USFS and CPW regarding time restrictions and relocation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 8&9. There are other sheds with large bird nests. Operator will need to consult with USFS and CPW regarding time restrictions and relocation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 10. Facing northwest at the sheds and equipment which are in disrepair..



Inspection Photos



Photo 11. Facing southeast at the west side of the location. This shed and fence are in disrepair with various unused unneeded supplies.



Inspection Photos



Photo 12. There are stained soils near this shed and engine compressor. There is chemical barrels with no containment and various debris laying on the ground.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 13. Facing northeast toward the well. The fence around the pumpjack is in disrepair and there is unused equipment stored near the well.



Inspection Photos



May 8, 2024
+38.203408,-103.141281

Photo 14. North side of the location facing southwest. There is unused pipe stored on location that needs to be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 15. Facing northeast. There are various unused equipment and supplies stored on location that needs to be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 16. North side of the location facing northwest. There are unused tanks stored on location which is impacting vegetation in this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 17. Facing southwest at the location. There appears to be impacted stained soil shown at red arrow.



Inspection Photos



Photo 18. Facing toward the west side of the location There is a large volume tank with no labeling and appear to be unused.



Inspection Photos



Photo 19. Facing toward the east side of the location. There is an tank with berm installed around the tank. The tank at red arrow is unused equipment.



Inspection Photos



Photo 20. There is oily sludge at the base of the tank that needs to be cleaned up and properly disposed.



Inspection Photos



Photo 21. East side of the location facing west. There is unused pipe stored on location and a tank that is tipped over.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources