

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2024

Submitted Date:

05/10/2024

Document Number:

714201013

FIELD INSPECTION FORM

Loc ID: 332756 Inspector Name: Santistevan, Brittani On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274396	WELL	SI	09/01/2022	GW	123-22523	JACK NOEL 1-18	SI
274397	WELL	SI	09/01/2022	GW	123-22522	JACK NOEL 5-2-18	SI

General Comment:

THIS IS A FOLLOW UP FIELD INSPECTION.

Inspected Facilities

Facility ID: 274396 Type: WELL API Number: 123-22523 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; previous inspection.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 02/08/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: WATER H2O

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 274397 Type: WELL API Number: 123-22522 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; previous inspection.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 02/08/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 16 Fluid Type: WATER H2O

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200914 AND IN REPOSE TO FIRR DOC#: 403766290. It appears all previous corrective actions assigned to this location have been resolved. For additional information please refer to previous inspection DOC#: 714200914 or FIRR DOC#: 403766290.	santistb	05/10/2024