

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2024

Submitted Date:

05/10/2024

Document Number:

714201017**FIELD INSPECTION FORM**Loc ID 332618 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247608	WELL	PR	06/01/2019	GW	123-15405	HSR-MNOOKIN 4-17	PR
284578	WELL	TA	06/08/2020	GW	123-23833	CRAVEN 31-17	TA

General Comment:[THIS IS A FOLLOW UP INSPECTION.](#)

Inspected Facilities									
Facility ID:	247608	Type:	WELL	API Number:	123-15405	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR; previous inspection								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	01/24/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	1	Fluid Type:	NONE					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	284578	Type:	WELL	API Number:	123-23833	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:	<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder:	PREVIOUS INSPECTION				
Comment:	TA								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	03/19/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	34	Fluid Type:	WATER H2O					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									
Comment	User		Date						
THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200916 AND IN REPONSE TO FIRR DOC#: 403753327. It appears all previous corrective actions assigned to this location have been resolved. For additional information please refer to previous inspection DOC#: 714200916 or FIRR DOC#: 403753327.	santistb		05/10/2024						