









**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #480890 Photo #3 Gas knockout equipment on the south east corner of the tank battery. A steady drip was observed leaking oil out of this vessel. POC was notified via email on 5/8/2024.**





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #480890 Photo #4 Gas knockout equipment on the south east corner of the tank battery. A steady drip was observed leaking oil out of this vessel. POC was notified via email on 5/8/2024.**







**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #480890 Photo #6 Gas knockout equipment on the south east corner of the tank battery. A steady drip was observed leaking oil out of this vessel. POC was notified via email on 5/8/2024.**





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #480890 Photo #7 Gas knockout equipment on the south east corner of the tank battery. A steady drip was observed leaking oil out of this vessel. POC was notified via email on 5/8/2024.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #480890 Photo #8 Gas knockout equipment on the south east corner of the tank battery. A steady drip was observed leaking oil out of this vessel. POC was notified via email on 5/8/2024.**





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #480890 Photo #9 Gas knockout equipment on the south east corner of the tank battery. A steady drip was observed leaking oil out of this vessel. POC was notified via email on 5/8/2024.**





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #480890 Photo #10 Gas knockout equipment on the south east corner of the tank battery. A steady drip was observed leaking oil out of this vessel. POC was notified via email on 5/8/2024.**





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #480890 Photo #11 Gas knockout equipment on the south east corner of the tank battery. A steady drip was observed leaking oil out of this vessel. POC was notified via email on 5/8/2024.**









**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #480890 Photo #13 AGT's, Oil on ground inside bermed area.







**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #480890 Photo #15 Tank #4, oil on the ground inside tank berm. Note: Bolts on hatch removed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #480890 Photo #16 note staining on ground.





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #480890 Photo #17 Tank #5 bolts removed from hatch. Note: oil on ground.





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #480890 Photo #18 pot hole. It is unknown what this pothole is for.









**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #480890 Photo #20 Inside tank battery bermed area, open pot hole, oil stained soil observed inside pothole.**





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #480890 Photo #21 drum on it's side inside berm. Drum was empty. IT is labeled as "purged groundwater"









**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #480890 Photo #23 trash bin on location, note: the top of the bin is open.





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #480890 Photo #24 trash on ground near trash bin.